

Maple Grove, MN

Walking Audit Summary

Audit Area	Assignment #1 Crossing Streets & Intersections	Assignment #2 Sidewalks	Assignment #3 Driver Behavior	Assignment #4 Safety	Assignment #5 Comfort & Appeal
#1 - Weaver Lk Rd					
#2 - Weaver Lk Rd	Difficult crossing for slow walkers	Cracked sidewalk @ Elm Creek NE corner			
	No raised bumps on NW corner @ Main				
#3 - Weaver Lk Rd	No raised bumps on north side at Pineview	Cracked sidewalk @ Main St SW corner	Some speeding noted		
		North side has many sidewalk cracks after Jonquil		Tunnel under @ Jonquil, but it is otherwise difficult to cross Weaver Lk	A lot of trash on this road
#4 - Weaver Lk Rd	Difficult crossing for slow walkers		Some speeding noted		
#5 - Zachary Ln	Difficult crossing for slow walkers				
#6 - Hemlock Ln	Crosswalk signal doesn't work @ 82nd	Sidewalk cracks along this route	Some speeding noted		
#7 - Hemlock Ln	Difficult crossing for slow walkers				
#8 - Hemlock/Elm Creek Blvd	Difficult crossing for slow walkers				
#9 - Hemlock Ln	Difficult crossing for slow walkers		Cars block crosswalk		
#10 - Main St	Difficult crossing for slow walkers		Right turners don't stop		
			Cars block crosswalk		
			2 cars turned into crosswalk while pedestrians were present		
#11 - Elm Creek Blvd					
#12 - Elm Creek Blvd	No raised bumps at Elm Creek & Vinewood	Sidewalks on SW side have many cracks			
	No raised bumps on west side of Elm Creek & 80th				
#13 - Elm Creek Blvd	No beep when crosswalk button is pushed	Crosswalk not striped on north side	Driver don't stop behind crosswalk	Pedestrians did not obey signals	
#14 - Grove Dr					
#15 - Wedgewood Ln	N/A	Some speeding beyond 30 mph			
#16 - Arbor Lakes Pkwy					
#17 - Arbor Lakes Pkwy	No crosswalk signs at Lakeview & Arbor Lakes Pkwy		Drivers don't slow for pedestrians in crosswalk		
#18 - Main St	Difficult crossing for slow walkers	North side crosswalk at Main St & Elm Creek blvd has large potholes			
		South side of walking path on this route has numerous large cracks			
#19 - Lake Drive N	Crosswalk at Lakeview & Kirkwood is in poor condition	Both crosswalks need signage	Some speeding by drivers		
#20 - Central Park Way					
#21 - Jonquil Lane			Some speeding by drivers		
#22 - Kirkwood Lane					
#23 - Main St	Cross on Main St at Town Green could use flashing lights to improve safety				
#24 - Maple Knoll Way	Only two out of 8 walk buttons at Elm Creek Blvd and Maple Knoll Way had audible beeps.	Some deep cracks next to Casa Corazon	Some cars speed through right turns		A bench in this area would be nice.
			Some speeding by drivers		Stoplight pedestal nearest fire station is in bad shape
#25 - 80th Circle N	No raised bumps at Wells Fargo north entrance	Severe water accumulation in front of Wendy's			
	Crosswalk at Main St and Arbor Lakes Pkwy has numerous cracks	Sidewalk on Main in front of City Hall has many large cracks			
#26 - Main St			Some minor speeding		
Maple Grove Pkwy & Grove Cir			Many cars stop on the crosswalk		
Bass Lake Rd	Crossing at Lanewood is difficult due to high car speeds		Many cars speeding	Park entrance at Lanewood does not have a safe crossing. Tunnel under the road is two blocks away.	Graffiti in the tunnel. Put there very recently